513702

To avoid breaking the float fulcrum pivot lug off the carburettor casting, it is important to use the correct 5/16 BS 1/4 W socket.

This is especially a risk on the MKI 2000 CD 150.

